

2021 Ford Mustang Mach-E

Weak Key Fob – Failure to Recognize

When Mach-E proximity key fob batteries become weak, the vehicle may have difficulty acknowledging its presence and not start.

Placing the fob in the designated area will aid in starting the vehicle.

The designated area in Mach-E is in on the front wall of the center console.



Immediately replace the weak key fob battery