

## 2017 Audi A3/ A3 E-Tron/S3/RS3

Weak Key Fob - Failure to Recognize



When an Audi proximity key fob battery becomes weak, the vehicle may have difficulty acknowledging its presence and not start.

Holding the fob near the designated area will aid in starting the vehicle.

The designated area in this model is on the right side of the steering column.

Immediately replace the weak key fob battery.

# 2017 Audi A4/S4/ A4 Allroad

Weak Key Fob - Failure to Recognize



When an Audi proximity key fob battery becomes weak, the vehicle may have difficulty acknowledging its presence and not start.

Holding the fob near the designated area will aid in starting the vehicle.

The designated area in this model is in the center console.

Immediately replace the weak key fob battery.

# 2017 Audi A5/S5

## Weak Key Fob - Failure to Recognize



When an Audi proximity key fob battery becomes weak, the vehicle may have difficulty acknowledging its presence and not start.

Holding the fob near the designated area will aid in starting the vehicle.

The designated area in this model is in the cup holder.

Immediately replace the weak key fob battery.

# 2017 Audi A6/S6

## Weak Key Fob - Failure to Recognize



When an Audi proximity key fob battery becomes weak, the vehicle may have difficulty acknowledging its presence and not start.

Holding the fob near the designated area will aid in starting the vehicle.

The designated area in this model is on the dash next to the multimedia player.

Immediately replace the weak key fob battery.

# 2017 Audi A7/S7/RS7

## Weak Key Fob - Failure to Recognize



When an Audi proximity key fob battery becomes weak, the vehicle may have difficulty acknowledging its presence and not start.

Holding the fob near the designated area will aid in starting the vehicle.

The designated area in this model is on the dash next to the multimedia player.

Immediately replace the weak key fob battery.

# 2017 Audi A8/S8

## Weak Key Fob - Failure to Recognize



When an Audi proximity key fob battery becomes weak, the vehicle may have difficulty acknowledging its presence and not start.

Holding the fob near the designated area will aid in starting the vehicle.

The designated area in this model is on the dash.

Immediately replace the weak key fob battery.

# 2017 Audi Q3

## Weak Key Fob - Failure to Recognize



When an Audi proximity key fob battery becomes weak, the vehicle may have difficulty acknowledging its presence and not start.

Holding the fob near the designated area will aid in starting the vehicle.

The designated area in this model is on the right side of the steering column.

Immediately replace the weak key fob battery.

# 2017 Audi Q5

## Weak Key Fob - Failure to Recognize



When an Audi proximity key fob battery becomes weak, the vehicle may have difficulty acknowledging its presence and not start.

Holding the fob near the designated area will aid in starting the vehicle.

The designated area in this model is in the cup holder.

Immediately replace the weak key fob battery.



---

## 2017 Audi Q7

### Weak Key Fob - Failure to Recognize



When an Audi proximity key fob battery becomes weak, the vehicle may have difficulty acknowledging its presence and not start.

Holding the fob near the designated area will aid in starting the vehicle.

The designated area in this model is in the center console.

Immediately replace the weak key fob battery.

# 2017 Audi TT - All Variants

Weak Key Fob - Failure to Recognize



When an Audi proximity key fob battery becomes weak, the vehicle may have difficulty acknowledging its presence and not start.

Holding the fob near the designated area will aid in starting the vehicle.

The designated area in this model is on the right side of the steering column.

Immediately replace the weak key fob battery.