

Supplier Alert – 2025 Porsche Macan EV

Porsche Canada has advised that when attempting to move a 2025 Porsche Macan EV, Service Providers must use dollies. Wheels cannot touch the ground due to risk of rolling when the vehicle is powered off.

NOT using dollies will cause damage to the vehicle due to very sensitive rear axles where complex motors are attached. As a result, please ensure that a truck is dispatched that has dollies. If a Driver does not have dollies at the scene, **DO NOT MOVE THE VEHICLE.**

Should you require assistance, please contact your Regional Manager or email calon_conrel@sykes.com.

Please note that this Supplier Alert has been loaded to the Service Provider Training Portal, and you can find the information located by taking a photo of the QR code below:

